

OUT52332

SECRET 201702Z

1963 NOV 20 17 59Z

PRIORITY

25X1

1. CAMERA B 8 WAS USED IN MISSION 3773 FLOWN ON 15 NOVEMBER 1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

NOV 1963

HFS

CJS

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: TWO STAINS THAT APPEAR TO HAVE BEEN CAUSED BY OXIDIZED DEVELOPER APPEAR ON FRAME 1707. THERE IS A MANUFACTURING SPLICE ON FRAME 495 WITH ASSOCIATED PLUS AND MINUS DENSITY STREAKS IN FRAMES 494 AND 495 AND A HEAVY CREASE EXTENDING TO FRAME 521. EMULSION BLISTERS ARE NUMEROUS THROUGHOUT THE MISSION.

Grace (File)

(EXAMPLE FRAME 982).

C. 9L SIDE: MINUS DENSITY DOTS ARE MINOR BUT NUMEROUS ON THE FIRST 130 FRAMES. CREASES ON FRAMES 162 THROUGH 167 ARE ASSOCIATED WITH A MANUFACTURING SPLICE ON FRAME 161. FRAMES 596-599 ARE AFFECTED BY CREASES WHICH ARE ASSOCIATED WITH A MANUFACTURING SPLICE ON FRAME 595. DRYING MARKS AND RANDOM, RANDOM, MINOR CREASES APPEAR ON FRAMES 1430 THROUGH 1451. THERE IS A FOGGED AREA 2" WIDE, PARALLEL TO THE MINOR AXIS, ON THE TRAILING EDGE OF FRAME 1775.

D. BOTH SIDES: EDGE FOG IS INTERMITTENT ON BOTH EDGES. PROCESSING STREAKS ARE CONTINUOUS THROUGHOUT THE MISSION. THERE ARE 2064 FRAMES ON EACH SIDE OF THIS MISSION.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVE:

Declassification Review by NGA/DoD

SECRET

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

A. PRINTING AND PROCESSING WERE GOOD.

B. PI SUITABILITY IS GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 55 PERCENT OF THIS  
MISSION.

S E C R E T

END OF MESSAGE

1